

1/6




FIG. 1




FIG. 1A




FIG. 2

2/6




FIG. 3




FIG. 3A




FIG. 4

029306
6/17/2005 8:55:56 PM

3/6




FIG. 5




FIG. 8




FIG. 7




FIG. 6

4/6




FIG. 9




FIG. 11




FIG. 10

6/6




FIG. 13




FIG. 14




FIG. 15




FIG. 16




FIG. 17




FIG. 18

5/6



FIG. 12C




FIG. 12A




FIG. 12D




FIG. 12B

Jun 17 05 06:15p

Jerry R. Potts

760-747-3951

p.41

LAST PAGE LEFT INTENTIONALLY BLANK